

**Kolak, Shari**

From: Montfort, Guy <Guy.Montfort@tetrattech.com>
Sent: Thursday, January 14, 2016 8:50 AM
To: Kolak, Shari
Cc: Mastrolonardo, Ray
Subject: RE: First Presbyterian Church - East Troy Site

Hi Shari - could you also check with Tom to see if there is a possibility they have any old fire inspection reports for 8 and 10 East Main from the era 1958-1979?

Also, as indicated in the EPA investigators' report there may be building permits or as built on file with the County if they are not with the City. I think it would be really useful to at least try to track down what is available and at least close the loop on that, if the EPA investigator did not already obtain these back in 2009. As I said, if we could confirm that the excavation was accomplished to 16 feet as described, or even find records from the construction company regarding how many truckloads of fill were brought in, that would tell us a lot. If your legal support could further discuss the construction with the Church - who was the architect, who was the builder etc. perhaps they could be tracked down. I think the old fire chief (Counts) - also may still be alive and available to talk to.

-----Original Message-----

From: Kolak, Shari [mailto:kolak.shari@epa.gov]
Sent: Wednesday, January 13, 2016 5:05 PM
To: Thomas Funderburg
Cc: Montfort, Guy
Subject: RE: First Presbyterian Church - East Troy Site

Thanks for trying.....

-----Original Message-----

From: Thomas Funderburg [mailto:thomas.funderburg@troyohio.gov]
Sent: Wednesday, January 13, 2016 2:40 PM
To: Kolak, Shari <kolak.shari@epa.gov>
Subject: RE: First Presbyterian Church - East Troy Site

Shari,

Sorry but I have not be able to find any resources regarding the information that you requested.

Tom

-----Original Message-----

From: Kolak, Shari [mailto:kolak.shari@epa.gov]
Sent: Monday, January 11, 2016 12:31 PM
To: Thomas Funderburg (thomas.funderburg@troyohio.gov)
Cc: Montfort, Guy; Mastrolonardo, Ray
Subject: Fw: First Presbyterian Church - East Troy Site

Hi Tom,

Would the City have any information on file related to the soil excavation that was done prior to construction of the First Presbyterian Church addition? Or to the moisture barrier liner that reportedly was installed below the basement foundation?

If so, how can I obtain this information? Not have any luck getting this info from the church. Thank you, Shari

Shari Kolak
Remedial Project Manager
U.S. EPA, Region 5
77 W. Jackson
Chicago, IL 60604